



# CAUTION



**Before setup, maintenance or repair, all sources of power to the machine must be secure with a locking device and tagged out.**